

Subject
Multifunction Power System Will Not Increase to Higher Speed

## System or Parts affected

- All Kubota Powered Multifunction Power Systems

## Symptom

Multifunction Engine will only run at low rpm speed, will not rev up to high rpm speed.

## Resolution

This issue is generally caused by a short in the wiring going to the throttle relay. This relay is located next to the radiator and can be subject to abrasion due to vibration. (Figure 1)




Figure 1

Check harness for exposed wires or shorts. Replace/repair as necessary (Figure 2)




Figure 2

Document	Version	Department	Revision Details	Revised by	Tech	Engineering	Implemented
EXT-MF-016	B	Tech	model/format updates	BDJ 12Jun2019	DB 14 Sept 2015	N/A	17 Sept 2015