

Airworthiness Directive

▼ Federal Register Information

This information is not available.

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 47-50-02

Airworthiness Directives; CESSNA Model 120 and 140 Airplanes
PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

47-50-02 CESSNA: Applies to 120 and 140 Aircraft Serial Numbers Up to and Including 14289.

Inspection required upon each 100 hours of operation until fuselage rear bulkhead (tail post) has been reinforced.

Inspect the lower right-hand corner of the cutout in the fuselage rear bulkhead for cracks which usually extend down to the rivet holes at the nearest anchor nut. If cracks

are found, install the new type bulkhead with reinforcement channel added per Cessna Drawing No. 0412169.

(Cessna Service Letter No. 46 dated July 31, 1947, covers this same subject.)

▼ **Footer Information**

▼ **Comments**

[FAA.gov Home](#) | [Privacy Policy](#) | [Web Policies & Notices](#) | [Contact Us](#) | [Help](#)

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)