

Airworthiness Directive

▼ Federal Register Information

This information is not available.

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 60-09-02

Airworthiness Directives; Forney Model Erco 415 Series and Aircoupe F-1 Aircraft
PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

60-09-02 FORNEY: Amdt. 137 Part 507 Federal Register April 30, 1960. Applies to Models Erco 415 Series and Aircoupe F-1 Aircraft Serial Numbers 1 Through 5678 Incorporating Electrol Hose Gear With Aluminum Scissors.

Compliance required not later than July 1, 1960.

Bolts used to attach the forged aluminum scissors to the electrol nose gear were found to be brittle. To preclude failure of these bolts and the danger of the nose wheel turning

crosswise during landing, the following shall be accomplished:

Replace bolts, P/N 415-34330, with AN 5-26 bolts, AN 960 washers (two per bolt) and AN 310-5 nuts. The tightened nut must not cause binding.

(Forney Service Bulletin No. 103 covers this same subject.)

▼ **Footer Information**

▼ **Comments**

[FAA.gov Home](#) | [Privacy Policy](#) | [Web Policies & Notices](#) | [Contact Us](#) | [Help](#)

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)