

Airworthiness Directive

▼ Federal Register Information

This information is not available.

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 55-22-02

Airworthiness Directives; ERCO 415-C, -CD and -D Aircraft

PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

55-22-02 ERCO: Applies to 415-C, -CD and -D Aircraft Serial Numbers 113 Through 2468 for Fuselage Tank Replacement; Serial Numbers 113 Through 2622 For Wing Tank Replacements.

Inspection required each 25 hours; replacement at time leakage discovered.

Unless the terneplate fuselage fuel tank has been replaced with a stainless steel tank and the terneplate wing fuel tanks replaced with aluminum alloy or stainless steel tanks,

the tanks should be inspected frequently for signs of leakage at intervals not greater than 25 hours. If tank leakage is observed, the tank should be replaced with one of stainless steel or aluminum alloy, as required, before the next flight.

Erco Service Department Bulletins No. 10 and No. 10A and Memorandums No. 31 and 43 pertain to the inspection and replacement of these tanks.

This supersedes AD 47-50-10.

▼ **Footer Information**

▼ **Comments**

FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)