

Airworthiness Directive

▶ Federal Register Information

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 47-10-40

Airworthiness Directives; LUSCOMBE Model 8 Series Aircraft

PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

47-10-40 LUSCOMBE: (Was Mandatory Note 11 of AD-694-4.) Applies to Model 8 Series Aircraft Serial Numbers 1934 to 2200 Inclusive.

Compliance required prior to May 1, 1947.

Determine if the attachment of the rudder control arm to the torque tube has been reinforced by a steel strap that extends completely around the torque tube and is securely welded to both the fore and aft flanges of the rudder control arms and the torque tube. If the reinforcing steel strap is not properly located and welded to both flanges, a repair should be made.

(Luscombe Service Bulletin No. 4-46 covers this same subject.)

▼ **Footer Information**

▼ **Comments**

Updated RGL applicability to match AD applicability; CAR
C-11-185

FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)