

Airworthiness Directive

▼ Federal Register Information

This information is not available.

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 46-37-01

Airworthiness Directives; Piper Models J3C-65, J3C-65S, and All PA-12
PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

46-37-01 PIPER: (Was Mandatory Note 12 of AD-691-02 and Mandatory Note 1 of AD-780-3.) Applies to J3C-65 and J3C-65S, Serial Numbers 14027 and Up and All PA-12.

Compliance required by November 1, 1946.

To prevent possible failure of the fuel strainer bowl, replace the present thin fuel strainer bowl gasket with a 1/8-inch thick cork and neoprene gasket supplied by Piper. The bowl seat nut should be tightened only finger tight. The bowl should be carefully examined

for signs of flaws or cracks and should be replaced if any are found.

(Piper Service Bulletin No. 89 dated July 11, 1946, covers this same subject.)

▼ **Footer Information**

▼ **Comments**

FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)