

Airworthiness Directive

▶ Federal Register Information

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 46-36-03

Airworthiness Directives; Piper Model PA-12 Aircraft
PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

46-36-03 PIPER: (Was Mandatory Note 2 of AD-780-3.) Applies Only to PA-12 Aircraft Serial Numbers 12-1 to 12-285, Inclusive.

Compliance required not later than next periodic inspection.

To prevent possible failure of the tailpipe and cracking of the muffler, install the additional brace tube, Piper P/N 10860 and new clamp, P/N 80002-28. The new brace will form, together with the original brace, a "V" instead of a single leg. A careful inspection of the muffler should be made and if any cracks are present, a new muffler should be installed.

(Piper Service Bulletin No. 92 dated August 7, 1946, covers this same subject.)

▼ **Footer Information**

▼ **Comments**

[FAA.gov Home](#) | [Privacy Policy](#) | [Web Policies & Notices](#) | [Contact Us](#) | [Help](#)

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)