

Airworthiness Directive

▶ Federal Register Information

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 46-36-02

Airworthiness Directives; Piper Model PA-12 Aircraft

PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

46-36-02 PIPER: (Was Mandatory Note 3 of AD-780-3.) Applies to PA-12 Aircraft Serial Numbers 12-1 to 12-207, Inclusive.

Compliance required prior to November 1, 1946.

Several instances have been reported of loosening of the cap screws attaching the air scoop to the carburetor on these aircraft, thus creating a hazard. These cap screws should be removed and drilled for safety wire. They should then be reinserted and safety wire installed.

(Piper Service Bulletin No. 90 dated July 17, 1946, covers this same subject.)

▼ **Footer Information**

▼ **Comments**

FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)