

## Airworthiness Directive

### ▼ Federal Register Information

This information is not available.

### ▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

**AD 54-19-01**

Airworthiness Directives; Piper Model PA-18A Aircraft  
**PDF Copy (If Available):**

### ▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

### ▼ Regulatory Information

**54-19-01 PIPER:** Applies to Models PA-18A and PA-18A Restricted Category Aircraft With Dusting Venturi, Up to and Including Serial Number 18-3752.

Compliance required not later than October 15, 1954.

There have been several instances of excessive CO concentration in the cockpit when the dusting venturi is used. Such contamination has serious adverse effects upon pilot reaction. To prevent CO from entering the cockpit, a new trim plate should be installed

and a new brake line cover plate should be placed over the brake line where the line enters the bottom of the fuselage.

(Piper Service Letter No. 225, dated August 23, 1954, covers the same subject.)

▼ **Footer Information**

▼ **Comments**

**FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help**

**Readers & Viewers:** [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)