

## Airworthiness Directive

### ▶ Federal Register Information

#### ▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

Amendment 39-1557; AD 72-24-02

Airworthiness Directives; Piper Model PA-28-140, PA-28-150, PA- 28-160, PA-28-S-160, PA-25 (150 HP) Airplanes

**PDF Copy (If Available):**

#### ▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

DATES: Effective November 17, 1972.

#### ▼ Regulatory Information

**72-24-02 PIPER:** Amendment 39-1557. Applies to Model PA-28-140, PA-28-150, PA-28-160, PA-28-S-160, PA-25 (150 HP) airplanes, equipped with Lycoming O-320 engines and Marvel Schebler carburetors Model MA-4SPA, Part Number 10-3678-32 certificated in all categories.

Compliance required within the next 10 hours' time in service after the effective date of this airworthiness directive, unless already accomplished:

To prevent power interruption as a result of abrupt throttle movement, accomplish the following:

(a) Attach the following operating limitation placard to the instrument panel near the throttle control in full view of the pilot using 1/8" minimum size type: "DO NOT OPEN THE THROTTLE RAPIDLY. (IDLE TO FULL THROTTLE IN 2 SECONDS MINIMUM.)" The placard may be fabricated by the owner/operator.

This amendment becomes effective November 17, 1972.

#### ▼ Footer Information

#### ▼ Comments

**FAA.gov Home** | **Privacy Policy** | **Web Policies & Notices** | **Contact Us** | **Help**

**Readers & Viewers:** [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)