

Airworthiness Directive

▶ Federal Register Information

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 64-24-05

Airworthiness Directives; Piper Model PA-25-235 Aircraft

PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

DATES: Effective October 24, 1964.

▼ Regulatory Information

64-24-05 PIPER: Amdt. 826 Part 507 Federal Register October 24, 1964. Applies to Model PA-25-235 Aircraft, Serial Numbers 25-02, 25-2000 through 25-2931.

Compliance required within 50 hours' time in service after the effective date of this AD unless already accomplished.

Air leaks, which permit entrance of engine fumes into the cockpit, exist in the area of the fuselage right main landing gear fittings. To correct this condition, accomplish the following:

Install seals, Piper Kit Number 756824 or FAA approved equivalent, at the front and

rear right main landing gear fittings as indicated on the sketch on the reverse side of Piper Service Bulletin No. 221 dated August 27, 1964.

(Piper Service Bulletin No. 221 dated August 27, 1964, pertains to this same subject.)

This directive effective October 24, 1964.

▼ **Footer Information**

▼ **Comments**

FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)