

ENGINEERING BULLETIN No. 10

As a safety measure to prevent possible icing of the lower end of the crankcase breather tube as installed on Model 8A aircraft, please have this tube cut off flush with the lower face of the grommet which insulates it from the top of the carburetor airscoop.