

IMMEDIATE ACTION

SERVICE



BULLETIN

NUMBER 95

September 11, 1946

SUBJECT: DEFECTIVE GLASS FUEL STRAINER BOWLS

**MODELS AFFECTED: J-3 Airplanes
SERIAL NO. 14027 THRU 19760**

Several cases of defective glass fuel strainer bowls have been called to our attention. These defects are in the form of distortions, internal air bubbles or indication of cold forming.

Therefore, we are requesting all owners to inspect their airplanes for defective bowls. If defective bowls are found they should be replaced by aluminum bowls, Piper No. 455 625. These aluminum bowls may be obtained through your local dealer, distributor, or through the Service Department of Piper Aircraft Corporation.

An appropriate entry should be made in the aircraft log book upon completion of this change.

End

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.