



SERVICE LETTER

No. 247

Piper Aircraft Corporation

April 15, 1955 S

TO: All Distributors, Dealers, Owners and Operators

SUBJECT: Tail Reinforcement PA-18A Agricultural Airplane


MODELS AFFECTED: All PA-18A airplanes up to serial 18-4122

During the service life of the PA-18A agricultural airplane, it has been found that under certain load conditions and certain types of maneuvering the bottom longerons in the tail area have become bent. On production airplanes serial 18-4123 and up the bottom longeron has been reinforced to prevent this bending action, and for all PA-18A airplanes in the field which fall within the above serial group, a service kit 754 092 has been developed and can be installed at the owner's convenience.

Kit 754 092 can be ordered through your nearest Piper distributor at a list price of \$2.40.

Very truly yours,

PIPER AIRCRAFT CORPORATION


Rolland Boardman
Service Manager