

SERVICE

LETTER

Service Letter No. 349

December 14, 1960

TO: Distributors, Dealers, Owners and Certified Service Centers

SUBJECT: Adjustment of Engine Support Bushings

MODELS AFFECTED: All PA-18, PA-22 and PA-25 series aircraft equipped with Lycoming engines

We have been advised by Lycoming Division of Avco Corporation, Williamsport, Pennsylvania, that it is permissible to use a torque value of 40 inch pounds to provide adequate tightness to maintain proper engine support in lieu of the linear dimension as previously specified. The mounting bushing must be free of oil and the bolt must move freely through the mount, using this torque value.

Very truly yours,

PIPER AIRCRAFT CORPORATION


Wes Holmes
Service Manager