

IMMEDIATE ACTION

**SERVICE**



**BULLETIN**

September 20, 1957

NUMBER 158

SUBJECT: Model PA-20 Name Plates

MODELS AFFECTED: All PA-20 Airplanes

It has been brought to our attention that the name plate on a PA-20 airplane was stamped with the incorrect model designation.

There may be more incorrect name plates in existence and it is therefore requested that all PA-20 name plates be inspected and those bearing the model designation "PA-20A" be removed and returned to the Factory Service Department for replacement.

It is further requested that a thorough examination be made of all pertinent aircraft papers such as flight manuals, weight and balance, repair and alteration, etc., and if the model designation "PA-20A" is evident, then those papers must also be returned for replacement or rider attachment.

Compliance with this Bulletin is requested prior to December 1, 1957.

End.

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA.. U. S. A.