

IMMEDIATE ACTION

SERVICE



BULLETIN

Service Bulletin No. 198

January 6, 1961

SUBJECT: Replacement of Tail Brace Clevises

MODELS AFFECTED: PA-22-108 Colt Aircraft - Serial Nos. 22-8000 to 22-8042 inclusive

DATE OF COMPLIANCE: Prior to but not later than the next 25 hours of operation

The tail brace clevises and bushings on the aircraft indicated by the above serial numbers are to be replaced.


The sketch on the reverse side of this Service Bulletin will indicate the location of the clevises and bushings to be changed.

Kit No. 754 381, consisting of six (6) clevises and four (4) bushings to comply with this Service Bulletin, will be forwarded by automatic factory distribution. The kit will be provided on a no charge basis. A compliance card is furnished with the kit for this modification. This card must be signed and immediately returned to the factory.

One hour warranty labor will be authorized upon receipt of a duly executed Warranty and Credit Claim form.

(over)

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.



SERVICE BULLETIN No 198