

IMMEDIATE ACTION

SERVICE



BULLETIN

Service Bulletin No. 264

December 22, 1967

Subject: Revision to Aircraft Flight Manual Supplement

Models Affected: PA-22S-135

Serial Numbers Affected: 22-807 to 22-2424 incl., (PA-22S-135 Scaplanes with auxiliary fuel tank installation only)

Compliance Date: Prior to but not later than the next periodic inspection

Reason For Bulletin: The flight manual supplement titled "Supplement No. 2 to aircraft flight manual dated October 23, 1952" concerning the installation of the optional auxiliary fuel tank on affected model aircraft may contain erroneous information.

Action Required: Inspect aircraft flight manual; if it contains supplement No. 2 dated October 23, 1952, contact your Piper dealer and obtain correct supplement (See "Material Required", below).

Material Required: Supplement No. 1 to aircraft flight manual dated May 14, 1954.

Availability of Parts: Piper Dealer

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.