

# SERVICE



# LETTER

Service Letter No. 143

May 5, 1950

**Subject:** Stabilizer Adjustment Cable Pulley Modification  
PA-20 Serials 20-1 to 20-28 incl., 20-30 to 20-35 incl.

**To:** All Distributors and Dealers

On PA-20 Piper Pacers, serials 20-29, 20-36 and up, the stabilizer adjustment cable fibre rub block, located over the cabin ceiling on the top of the steel tubular cross member between the wing hinge fittings, was changed to a pulley arrangement which helped to prevent cable slippage and possible cable fraying.

A stabilizer adjustment cable pulley kit, number 752 184, is now available at a list price of \$1.50. This kit can be installed through the zipper opening in the cabin ceiling upholstery. There is a diagram with each kit to show how it is to be installed, and the estimated installation time is approximately one (1) hour.

Very truly yours,

PIPER AIRCRAFT CORPORATION

A handwritten signature in cursive script, appearing to read "Rolland Boardman".

Rolland Boardman  
Service Manager

RB:dh

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.