

SERVICE



LETTER

Service Letter No. 153

July 12, 1950

To: All Distributors and Owners of the PA-20 Model Airplanes

Subject: PA-20 Windshield Supports

It has been brought to our attention that many owners of the PA-20 Pacer are not keeping the windshield support studs adjusted properly.

We invite your attention to the fact that, if these studs are not adjusted so that the little rubber pad rests lightly against the inside surface of the windshield, excessive vibration and flexing will cause the windshield to crack within the area of the support studs.

We suggest that a careful inspection of your windshield be made to determine whether or not cracks have appeared. In the event there are indications of cracks, the windshields should be replaced.

Very truly yours,

PIPER AIRCRAFT CORPORATION

A handwritten signature in cursive script, appearing to read "Rolland Boardman".

Rolland Boardman
Service Manager

RB:df

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.