

# SERVICE



# LETTER

Service Letter No. 214

November 17, 1953

To: All Distributors, Dealers, Operators and Owners

Subject: Navigation Light Switch (Service Letter #209)

Models Affected: All Models

In our Service Letter Number 209 we submitted information to the field which stated that a new type navigation light switch, Piper part number 484 575, was available as a replacement for the light weight navigation light switch which has been used on the PA-20 and PA-22 Models for the past two years.

Several reports have been received from the field stating that the light weight light switches have been burning out, causing smoke to be present in the cockpit. Since smoke in the cockpit can be hazardous, we would like to recommend that the heavy duty switch be installed at your earliest convenience.

This switch can be obtained from your nearest Distributor or Dealer at the list price of \$5.50\*\*.

Very truly yours,

PIPER AIRCRAFT CORPORATION

Rolland Boardman  
Service Manager

RB:lh

PIPER AIRCRAFT CORPORATION. LOCK HAVEN, PA., U. S. A.