



SERVICE LETTER

No. 243

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

February 8, 1955

TO: All Distributors, Dealers, Owners and Operators

SUBJECT: PA-22 Engine Mount

MODELS AFFECTED: All PA-22's

We have received three official reports that fatigue cracks have appeared in the PA-22 engine mounts in the vicinity of the welds at both the firewall and the engine attachment points.

It is requested that each PA-22 owner inspect his engine mount at his earliest convenience, to determine whether or not **there** is any evidence of fatigue cracks in the aforementioned areas. If cracks are present, effective repairs should be made in accordance with the CAM-18.

Very truly yours,

PIPER AIRCRAFT CORPORATION

Rolland Boardman
Service Manager

RB:m:h