

SERVICE BULLETIN

Stinson Division

TITLE: Inspection - Cabin Sliding Window

BULLETIN NO. 253

MODELS AFFECTED: 108-1 through 108-1989

PAGE 1 of 1

DATE: September 2, 1947

Gentlemen:

As a precaution against possible cracking of the sliding window, at the knob, we recommend the following correction on airplanes in the above category.

Remove the knob and re-install using two 5/8" washers, one on each side of the window panels.

This change has been incorporated on all airplanes serial number 108-1990 and up.

This bulletin is not mandatory, and we will not participate in any direct labor involved in making this modification.

Yours very truly,

STINSON DIVISION

Rolland Boardman
Service Manager

RB:df

Note: This bulletin originally written and signed by George Martin