

SERVICE LETTER

Stinson Division
Consolidated Vultee Aircraft Corporation
Wayne, Michigan

TO: Distributors, Direct Factory Dealers and
Distributor's Dealers

LETTER NO: 48

Page 1 of 1

TITLE: Removal of Lens and Dome Light and Radio
Grill - 1947 Model

Date: February 20, 1947

Gentlemen:

We have found, through our field service organization and in conjunction with the manufacturer of the assembly, that there is a possibility of breakage through incorrect removal of the dome light lens.

The following procedure is recommended:

Pry plastic lens from lamp body, using a knife blade or similar tool. Tool should be inserted in the exact center at right or left side of lens parallel to the length.

We assume you will want to pass this information on to your service organization.

Yours very truly,

Stinson Division
Consolidated Vultee Aircraft Corporation

George Martin
Service Manager