

SERVICE LETTER

September 8, 1994

**SERVICE INFORMATION LETTER NO. 79
SUBJECT: OPERATING LIMITATIONS PLACARD
(MODEL 108 ONLY)**

It has come to our attention that the wording on Operating Limitations Placard, P/N 108-8741001-6, used on Stinson Model 108 (S/N 1-742 except S/N 11) does not agree with the placard description in the Type Certificate Data Sheet (TCDS) A-767. The critical discrepancy is that the 108-8741001-6 placard indicates that loops and barrel rolls may be performed. However, these maneuvers are not listed as eligible in TCDS A-767 or the Approved Operating Limitations Manual. In the interest of safety, and to bring the placard into agreement with the TCDS, Univair is revising the placard drawing to eliminate loops and barrel rolls.

Revised placards are being supplied at no charge to all owners of Stinson Model 108 airplanes. Existing placards (either original equipment or Univair manufactured replacement type) are to be replaced with the revised placard supplied by Univair as soon as possible. This placard change applies only to Stinson Model 108 airplanes. Stinson Model 108-1, 108-2, 108-3 and 108-5 airplanes are not affected. For more information concerning this service difficulty, please contact the Univair Engineering Department.