Airworthiness Directive

Federal Register Information

[Federal Register: January 18, 1967]

Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

Amendment 39-343; **AD 67-03-02**

Airworthiness Directives; Champion Models 7ECA, 7GCAA, 7GCBC, and 7GCB Airplanes

PDF Copy (If Available):

Preamble Information

AGENCY: Federal Aviation Administration, DOT

DATES: Effective January 18, 1967.

Regulatory Information

67-03-02 CHAMPION: Amdt. 39-343 Part 39 Federal Register January 18, 1967. Applies to Models 7ECA, 7GCAA, 7GCBC, and 7GCB Airplanes.

Compliance required as indicated.

(a) Until the lower bracket supporting the fuel shutoff valve is modified in accordance with Champion Service Letter No. 73, acrobatic maneuvers in aircraft of these models

may not be performed.

(b) Within 25 hours' time in service after the effective date of this AD, the lower bracket supporting the fuel shutoff valve must be modified by the installation of Champion P/N 1-9863 in accordance with the instructions contained in Champion Service Letter No. 73 dated January 13, 1967.

This directive effective January 18, 1967.

Footer Information

Comments

FAA.gov Home | **Privacy Policy** | **Web Policies & Notices** | **Contact Us** | **Help**

Readers & Viewers: PDF Reader | MS Word Viewer | MS PowerPoint Viewer | MS Excel Viewer | WinZip