

## Airworthiness Directive

### ▼ Federal Register Information

This information is not available.

### ▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

### AD 47-30-01

Airworthiness Directives; Aeronca Model 7AC and 11AC Airplanes  
**PDF Copy (If Available):**

### ▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

### ▼ Regulatory Information

**47-30-01 AERONCA:** (Was Mandatory Note 3 of AD-759-3 and Mandatory Note 3 of AD-761-3.) Applies Only to Serial Numbers 7AC-1 to 4795, Inclusive, and 11AC-1 to 11AC- 502, Inclusive.

Compliance required not later than November 1, 1947.

To prevent failure of lift strut wing fitting due to tie-down loads, replace front lift strut wing attachment fittings with Aeronca No. 2-893 fittings. (Aeronca Service Helps and

Hints No. 13 dated August 14, 1946, and supplement thereto covers this same subject.)

▼ **Footer Information**

▼ **Comments**

**FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help**

**Readers & Viewers:** [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)