

Airworthiness Directive

▼ Federal Register Information

This information is not available.

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 48-25-02

Airworthiness Directives; CESSNA Model 120 and 140 Airplanes
PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

48-25-02 CESSNA: Applies to All 120 and 140 Aircraft Equipped With Cessna Welded Exhaust Muffler Assemblies.

Inspection required each 25 hours of operation.

Remove the carburetor air heater muff and cabin heater muff and inspect the muffler assemblies for any evidence of cracks paying particular attention to the areas of the mufflers and stacks adjacent to where the exhaust stacks and tailpipe are welded to the

muffler assembly. The present placard calling for inspection of the mufflers every 100 hours should be revised to call for this inspection every 25 hours. This directive is intended to apply to only those aircraft equipped with exhaust muffler assemblies that are fabricated by welding exhaust stacks to muffler.

▼ Footer Information

▼ Comments

[FAA.gov Home](#) | [Privacy Policy](#) | [Web Policies & Notices](#) | [Contact Us](#) | [Help](#)

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)