

Airworthiness Directive

▼ Federal Register Information

This information is not available.

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 47-06-10

Airworthiness Directives; CESSNA Models 120 and 140 Airplanes
PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

47-06-10 CESSNA: (Was Mandatory Note 6 of AD-768-4.) Applies to 120 and 140 Aircraft Serial Numbers Up to and Including 9669.

Compliance required prior to April 1, 1947.

Install carry-through bar between the ends of the aileron control chain that is installed at the top of the control "T" to make a continuous loop at this chain installation so that both control wheels operate positively in the same direction. This is necessary to prevent

possible locking of aileron system at full throw.

(Cessna Service Letter No. 17 dated September 19, 1946, covers this same subject.)

▼ **Footer Information**

▼ **Comments**

FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)