

Airworthiness Directive

▼ Federal Register Information

This information is not available.

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 46-44-04

Airworthiness Directives; CESSNA Model 120 and 140 Airplanes
PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

46-44-04 CESSNA: (Was Mandatory Note 4 of AD-768-4.) Applies to 120 and 140 Aircraft Serial Numbers Up to and Including 9721.

Replacement required prior to December 1, 1946.

All U. S. Rubber Co. P-212 and P-212L Series flexible ducts installed in the carburetor hot air system should be replaced by U. S. Rubber Co. P-208-S duct or P-208 duct coated with neoprene by Cessna or its distributors.

(Cessna Service Letter No. 16-120 and 140 covers this same subject.)

▼ **Footer Information**

▼ **Comments**

FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)