

Airworthiness Directive

▼ Federal Register Information

This information is not available.

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 47-20-09

Airworthiness Directives; ERCO Model 415-C, -CD and -D Aircraft
PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

47-20-09 ERCO: (Was Service Note 1 of AD-718-6.) Applies to 415-C, -CD and -D Aircraft.

Compliance required at each 100-hour inspection and immediately after each electrical system malfunction.

Check the operation of the voltage regulator by observing the ammeter reading after starting and until the battery becomes charged. A normal operation would indicate a charging rate up to 11-13 amperes for periods of time up to 20 minutes after starting. The charging rate should reduce to 2 amperes or less within 2 hours of operation. (Ercoupe Service Department Memorandum No. 23 covers this same subject.)

▼ **Footer Information**

▼ **Comments**

FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)