

Airworthiness Directive

▼ Federal Register Information

This information is not available

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 47-20-04

Airworthiness Directives; ERCO Model 415C, -CD and -D Aircraft

PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

47-20-04 ERCO: (Was Mandatory Note 12 of AD-718-6.) Applies to 415-C, -CD and -D Aircraft Serial Numbers 113 Through 4399.

To be accomplished prior to August 1, 1947.

A positive locking device must be installed on the zipper in the baggage compartment bottom to prevent its opening and permitting articles to fall through and foul the

controls.

(Erco's Ercoupe Service Department Bulletin No. 17 dated January 6, 1947, covering this same subject, provides a satisfactory method for safetying the bottom baggage compartment zipper.)

▼ **Footer Information**

▼ **Comments**

FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)