

## Airworthiness Directive

### ▼ Federal Register Information

This information is not available.

### ▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

**AD 46-23-01**

Airworthiness Directives; ERCO Model 415-C, -CD and -D Aircraft  
**PDF Copy (If Available):**

### ▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

### ▼ Regulatory Information

**46-23-01 ERCO:** (Was Mandatory Note 4 of AD-718-6.) Applies Only to 415-C, -CD and -D Aircraft Serial Numbers 113 to 362, Inclusive.

To be accomplished within next 50 hours of operation.

Trouble in service has indicated the necessity for replacing the original muffler on the serial numbers listed above with a new muffler, Erco P/N 145-40517.

(Erco Service Department Memorandum No. 7 dated February 1, 1946, covers this same subject.)

▼ **Footer Information**

▼ **Comments**

**FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help**

**Readers & Viewers:** [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)