

## Airworthiness Directive

### ▶ Federal Register Information

#### ▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

**AD 48-09-03**

Airworthiness Directives; LUSCOMBE Model 8 Series Airplanes  
**PDF Copy (If Available):**

#### ▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

#### ▼ Regulatory Information

**48-09-03 LUSCOMBE:** Applies to Model 8 Series Airplanes Below Serial Number 5682 Equipped With Kollsman Airspeed Instruments.

Compliance required by April 1, 1948.

To obtain more accurate airspeed readings remove small baffle LAC P/N 181112, which is attached to the fuselage at the airspeed static tube opening. Installation of this baffle provides inaccurate airspeed readings ranging from approximately +6 m.p.h. at stall to approximately +15 m.p.h. at minimum trim speed.

▼ **Footer Information**

▼ **Comments**

**FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help**

**Readers & Viewers:** [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)