

## Airworthiness Directive

### ▼ Federal Register Information

This information is not available.

### ▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

**AD 58-12-02**

Airworthiness Directives; Piper All Models J-3, PA-11, PA-15, PA-16 and PA-17 Aircraft  
**PDF Copy (If Available):**

### ▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

### ▼ Regulatory Information

**58-12-02 PIPER:** Applies to All Models J-3, PA-11, PA-15, PA-16 and PA-17 Aircraft.

Compliance required not later than July 15, 1958.

There is a possibility that some aileron hinge reinforcing brackets P/N 10931-02 supplied to the field during the past three years were fabricated from aluminum instead of steel. Brackets, which have been replaced since June 1954, must be inspected to determine the type of material. All aluminum brackets are to be removed and replaced

with steel brackets.

(Piper Service Bulletin No. 165 covers this subject.)

▼ **Footer Information**

▼ **Comments**

**[FAA.gov Home](#) | [Privacy Policy](#) | [Web Policies & Notices](#) | [Contact Us](#) | [Help](#)**

**Readers & Viewers:** [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)