

Airworthiness Directive

▶ Federal Register Information

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 47-50-03

Airworthiness Directives; Piper Model J3, J3C Series, J3F Series, J3L Series and J3P Aircraft

PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

47-50-03 PIPER: Applies to J3, J3C Series, J3F Series, J3L Series and J3P.

Inspection required after each 100 hours of operation.

Inspect the front and rear canvas seat installations and note the condition of canvas, eyelets, and lacing. Any parts showing signs of wear, tearing, fraying or substandard material the failure of which could cause possible interference with the control system should be replaced. Check the tautness of the canvas to insure that position clearance with all parts of the elevator control system exists when the seats are occupied.

(Piper Service Bulletin No. 45 covers this same subject.)

▼ **Footer Information**

▼ **Comments**

[FAA.gov Home](#) | [Privacy Policy](#) | [Web Policies & Notices](#) | [Contact Us](#) | [Help](#)

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)