

## Airworthiness Directive

### ▶ Federal Register Information

#### ▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

**AD 48-14-01**

Airworthiness Directives; Piper Model PA-12 Aircraft  
**PDF Copy (If Available):**

#### ▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

#### ▼ Regulatory Information

**48-14-01 PIPER:** Applies to PA-12 Aircraft Serial Numbers 12-1 Through 12-1869; 12-1872; 12-1873; 12-1878; 12-1879; 12-1881; 12-1883; 12-1885 Through 12-1921; 12-2001 Through 12-2008; 12-2010 Through 12-2012; 12-2016; 12-2017; 12-2036 Through 12-2038; 12- 2042; 12-2043; 12-2047; 12-2050; 12-2051.

Compliance required prior to August 1, 1948.

To prevent possible fuel leakage at the connection of the elbow fitting with the rear fuel valve, replace elbow with Piper P/N 11610.

(Piper Service Bulletin No. 104 dated January 30, 1948, covers this same subject.)

▼ **Footer Information**

▼ **Comments**

**FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help**

**Readers & Viewers:** [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)