

Airworthiness Directive

▶ Federal Register Information

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 48-13-03

Airworthiness Directives; Piper Model PA-12 Airplanes
PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

48-13-03 PIPER: Applies to PA-12 Airplanes With Battery Holddown of Metal Bracket With Fiber Insulation at Its End.

Compliance required by October 1, 1948.

To eliminate battery short circuits caused by defective battery holddown brackets, replace brackets by wood blocks, Piper P/N 84682-3 and 84682-9 or equivalent. (Piper Service Bulletin No. 105 dated February 18, 1948, covers this same subject.)

▼ **Footer Information**

▼ **Comments**

FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)