

Airworthiness Directive

▶ Federal Register Information

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 51-09-03

Airworthiness Directives; Taylorcraft All Series Below Serial Number 13001

PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

51-09-03 TAYLORCRAFT: Applies to All Series Aircraft Below Serial Number 13001 Incorporating a Pushpull Type Fuel Shutoff Control.

Compliance required not later than June 1, 1951.

To prevent accidental operation of the fuel shutoff valve during flight, a safety device must be installed on this control. The device is to prevent inadvertent operation of the fuel shutoff valve by requiring a definite and positive movement by the pilot before the control can be operated. Taylorcraft P/N B12-947-3 or equivalent is considered satisfactory. P/N B12-947 which was previously installed in some Taylorcraft airplanes must be replaced by this improved part.

(Taylorcraft Service Bulletin No. 66 dated December 6, 1950, covers this same subject.)

This supersedes AD 47-13-01.

▼ **Footer Information**

▼ **Comments**

FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)