

Date: 3-26-65

ALON 

SERVICE BULLETIN

NO. SB-4

Model: A2

Serials: A-2 and A-3

Subject: Identification Plate Fastening

To meet the F.F.A. requirements in part 45:13. It will be necessary for you to replace the four (4) sheet metal screws attaching your aircraft identification plate on with rivets or blind rivets.