

Date 5/3/66

ALON 

SERVICE BULLETIN

NO. SB-10

Model: A2

Serials: A-2 and on

Subject: More frequent inspection of fuselage fuel tank.

From the interior of the aircraft, frequently check for leakage or seepage of the fuselage fuel tank. Check all plumbing connections for proper tightness and weld seams of the tank for possible cracks. Presence of red staining will indicate a leak or seepage exists and will indicate its point of origin.

Over-filling of the tank may also cause red staining. A thorough check should be made to determine the origin of a leak or seepage.

Any leak should be corrected before operating the aircraft.