

1. In accordance with the C.A.A. specification, a placard titled "INTENTIONAL SPINS PRO-HIBITED," must be installed in full view of the pilot on all 415-C or CD Ercoupes that have rudder pedals. Therefore, we are supplying a card with the above wording centered on it and one oblong transparent plate, as part of the SK-21.

2. To replace the oblong placard used on early Ercoupes, remove the name plate 415-51007 stating "THIS AIRPLANE CHARACTERISTICALLY INCAPABLE OF SPINNING." Center the transparent plate over the wording "INTENTIONAL SPINS PROHIBITED" and cut the card evenly around the plastic. Secure the plastic, with the card underneath it, to the instrument panel with original hardware. 3. For later model Ercoupes with the round plastic plate 415-51143, remove the wording "THIS AIRPLANE CHARACTERISTICALLY IN-CAPABLE OF SPINNING" from the rear of the plate with a sharp knife and then polish with a fine rubbing compound. Center this dial over the wording "INTENTIONAL SPINS PROHIB-ITED," cut card and replace with original hardware.

4. Models D, E and G do not require any additional placards for they have one stating, "THIS AIRPLANE CHARACTERISTICALLY INCAPABLE OF SPINNING--NO ACROBATIC MANEUVERS ARE APPROVED--THIS AIRPLANE MUST BE OPERATED IN COMPLIANCE WITH THE AP-PROVED OPERATING LIMITATIONS."