

ENGINEERING BULLETIN No. 14

Fuel Line Change

Aircraft affected: All Luscombe aircraft equipped with fuel injectors, up to and including Serial No. 1659.

All Luscombe aircraft Model 8A and 8B equipped with carburetors, Serial Numbers 1362 to 1658 inclusive.

Fuel line failures have occurred just aft of the firewall, which have led us to make a change at our factory, and to recommend that you make the same

change on any and all subject aircraft in your possession immediately. The Civil Aeronautics Administration will require that our recommendation be complied with prior to annual relicensing, and that pertinent notations have been made in the log book. We illustrate the change by sketch below.

Should you so desire, we would be glad to send you the steel tube, the hose connector and liner and a pair of clamps at a net price of \$0.40 for the lot including postage.

