

IMMEDIATE ACTION

SERVICE



BULLETIN

August 26, 1946

Bulletin No. 94

SUBJECT: REPLACEMENT OF GLASS FUEL STRAINER BOWLS

TO: ALL OWNERS OF PIPER PA-12 AIRPLANES
SERIAL NOS. 12-1 thru 12-286
12-288 thru 12-297
12-299 thru 12-302
12-304 thru 12-311
12-316, 12-318, 12-323
thru 12-326, 12-329 and
12-331

It has been brought to our attention that several cases of cracked fuel strainer bowls have occurred in service.

Therefore, it is necessary that an aluminum bowl be installed on all PA-12 airplanes to replace the glass bowl.

The aluminum fuel strainer bowl, Piper No. 455 625, may be obtained from your local dealer, distributor or through the Service Department of Piper Aircraft Corporation.

An appropriate entry should be made in the aircraft log book upon completion of this change.

If you have sold your airplane, please forward this bulletin to the present owner.

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.