

# SERVICE



# LETTER

Service Letter No. 203

May 7, 1953

To: All Distributors, Dealers and Owners

Subject: Weight and Balance Form

Models Affected: All PA-12 Aircraft


It has been brought to our attention that the propeller installation arm in the PA-12 Equipment List is at -52 inches, whereas this arm should actually be -62 inches.

The correction to -62 inches can be made in ink on your present Weight and Balance Form, or new blank forms can be obtained by writing to the Service Department of Piper Aircraft Corporation, Lock Haven, Pennsylvania.

If weight and balance computations have been made using the incorrect -52 inch figure, the computations should be corrected, using the correct figure.

Very truly yours,

PIPER AIRCRAFT CORPORATION

  
Rolland Boardman  
Service Manager

RB:lh

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.