

# SERVICE



# LETTER

Service Letter No. 189

April 17, 1952

TO: Distributors, Dealers and Owners

SUBJECT: Tail Wheel Springs

MODELS AFFECTED: All PA-18A Airplanes with Serial Numbers  
Prior to Serial Number 18-1327

The tail wheel spring system on the PA-18A Agricultural airplane has been changed in production to incorporate the use of one (1) additional long spring leaf, part number 12567-04. The reason for the addition of this spring is to prevent anticipated damage to the rudder while operating with heavy loads in rough terrain.

It is suggested that all PA-18A airplanes with serial numbers prior to serial number 18-1327 which are now in the field be modified to incorporate this change. We have a kit, number 752 237, which is available at No Charge.

Very truly yours,

PIPER AIRCRAFT CORPORATION

  
Rolland Boardman  
Service Manager

RB:lh

PIPER AIRCRAFT CORPORATION. LOCK HAVEN, PA., U. S. A.