



*Customer Services*

# SERVICE LETTER

No. 242A

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

February 20, 1959

---

TO: All Distributors, Dealers, Owners and Operators

SUBJECT: Special Air Filter Kits, PA-18A

SERIAL NUMBERS AFFECTED: See Below

This letter supersedes Service Letter No. 242 dated February 8, 1955.

In isolated sections of the United States and in some foreign countries, operators of the PA-18A Agriculture airplane have been experiencing difficulty in preventing sand and dirt from entering the engine through the carburetor air filter.

Sand and dirt will drastically reduce the normal service life of an engine and with this thought in mind, we have developed a new air filter installation which takes carburetor air from the top of the engine cowl instead of the bottom.

The following kits may be obtained through your nearest Piper distributor or dealer at the list price of \$125.00\*.

754 071 Kit - Special Carburetor Air Box Installation for PA-18A "135" airplanes from serial number 18-3786 and up.

754 072 Kit - Special Carburetor Air Box Installation for PA-18A "135" airplanes from serial number 18-3014 to 18-3785 inclusive.

754 073 Kit - Special Carburetor Air Box Installation for PA-18A "135" airplanes to serial number 18-3013 inclusive.

Very truly yours,

PIPER AIRCRAFT CORPORATION

Rolland Boardman  
Service Manager

RB:mm