

SERVICE



LETTER

Service Letter No. 146

June 1, 1950

Subject: Front Seat Frame Revision, PA-20 Serials
20-1 to 20-256 inclusive and 20-258

To: All Distributors and Dealers

There has been a slight change in the front seat bottom of the PA-20 Piper Pacer; part of this change being the lengthening of the seat guide which is welded to both the right and left side of the seat frame in order to effect a more positive engagement of the seat at the front attaching point.

The PA-20 seats in the field can be altered to incorporate this change by welding one additional seat guide, Part Number 11863-5, to each side of the seat frame in front of and adjacent to the existing guide. Part 11863-5 is available at a list price of 10¢.

Very truly yours,

PIPER AIRCRAFT CORPORATION

Rolland Boardman
Service Manager

RB:df1

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.