SERVICE

LETTER

STINSON DIVISION
Consolidated Vultee Aircraft Corporation
Wayne, Michigan

TO: Distributors, Direct Factory Dealers

LETTER NO. 60

and Distributor's Dealers

PAGE 1 of 1

TITLE: Use of Radio When Starting Engine

DATE: July 11, 1947

Gentlemen:

It is recommended that the radio be turned off during the time that the engine starter is being used. Simultaneous operation of the engine starter and the radio may result in reducing the life or cause complete failure of the radio vibrator due to the drop in voltage experienced when the starter is used.

Yours very truly,

STINSON DIVISION
Consolidated Vultee Aircraft Corporation

George Martin Service Manager

GM: LJA