

Summary of FAA Supplementary Type Certificates  
for Univair Aircraft and the  
Stinson 108 Series.  
T.C. A-767

[Stinson STC List.xls](#)

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	REG.	STC HOLDER
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA1-30	Conversion of wing panels from fabric to alclad panels.  Issued, 01/29/1957	NE-NY	Skycraft Design, Inc. 85 North Main St. Yardley, PA 19067
Stinson 108-3 T.C. A-767	SA1-48	Installation of Edo 249-2870 floats.  Amended, 01/01/1960	NE-NY	James R. Blakely P.O. Box 53 Westchester Station Bronx, NY 10461
Stinson 108 Series T.C. A-767	SA1-258	Conversion of aileron covering from fabric to alclad panels.  Reissued, 01/14/1983	NE-NY	Skycraft Design, Inc. 85 North Main St. Yardley, PA 19067
Stinson 108 Series T.C. A-767	SA1-374	Installation of Fram lube oil filter Model PB55-1.  Amended, 09/11/1967	NE-B	Fram Aerospace Division of Fram Corp. 750 School St. Pawtucket, RI 02860
Stinson 108 Series T.C. A-767	SA2-952	Installation of fiberglass covering.  Reissued, 09/10/1996	SW-FW	Razorback Fabrics, Inc. 2179 Elmont Road Maynard, AR 72444-9688
Stinson 108 Series T.C. A-767	SA3-27	Covering of wings .020-inch 24 ST. alclad.  Issued,	CE-C	Howard Aviation, Inc P.O. Box 1287 Peoria, IL 61601
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA3-366	Installation of Wipaire Skis Model 3000 (Aircraft Skis) (FluiDyne) (Fli-Lite) main and Model 1000 tail skis. Reissued, 02/16/1993	CE-C	Wipaire, Inc. 1700 Henry Ave. South St. Paul, MN 55075
Stinson 108 Series T.C. A-767	SA3-398	Fiberglass plastic covering of all fabric surfaces.  Issued, 01/01/1960	CE-C	John H. Fallon 601 Woodward Heights Blvd Ferndale, MI 48220
Stinson 108 Series T.C. A-767	SA3-423	Installation of CT-3000 tail ski on airplanes equipped with Scott 3200 or 3400 tail wheels.  Reissued, 02/16/1993	CE-C	Wipaire, Inc. 1700 Henry Ave. South St. Paul, MN 55075
Stinson 108 Series T.C. A-767	SA3-606	Complete recover of all fabric surfaces with dacron fabric.  Issued,	CE-C	Downer Aircraft Ind., Inc. Municipal Airport Alexandria, MN 56308
Stinson 108 Series T.C. A-767	SA4-46	Lycoming O-435-1 engine, accessories, and Hartzell HC-12X20-8D propeller.  Issued,	NM-LA	Serv-Aero Engineering, Inc. P.O. Box 96 Dos Palos, CA 93620
Stinson 108 Series T.C. A-767	SA4-148	Conversion of aircraft electrical system to 24 volts and/or installation of Franklin 6A4-165- B3 engine. Reissued, 10/05/1979	NM-LA	Dean D. Brubaker P.O. Box 84409 861 South Bringham Ave. Los Angeles, CA 90073
Stinson 108 Series T.C. A-767	SA4-224	Application of fiberglass covering.  Issued,	NM-LA	Whitehall Pacific Avia., Inc. P.O. Box 31174 County Airport Ventura, CA 93001

Summary of FAA Supplementary Type Certificates  
for Univair Aircraft and the  
Stinson 108 Series.  
T.C. A-767

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	REG.	STC HOLDER
Stinson 108 Series T.C. A-767	SA4-284	BN-1 propeller spinner.  Issued,	NM-LA	Raymond M. Stits 3665 Bloomington Blvd. Riverside, CA 92502
Stinson 108-2, 108-3 T.C. A-767	SA4-398	Installation of Lycoming O-435-C engine. (108-3 Landplane)  Amended, 07/10/1975	NM-LA	Serv-Aero Engineering, Inc. 37 Mortensen Ave. Municipal Airport Salinas, CA 93905
Stinson 108 Series T.C. A-767	SA4-630	Eonite covering of wings, fuselage and ailerons.  Issued, 01/01/1970	NM-LA	William C. Lott P.O. Box 632 Shafter Airport Bakersfield, CA 93300
Stinson 108 Series T.C. A-767	SA4-760	Ceconite 101 covering of wings, fuselage and ailerons.  Issued,	NM-LA	Cooper Engineering Corporation P.O. Box 3428 Van Nuys, CA 91408
Stinson 108 Series T.C. A-767	SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.  Issued,	NM-LA	Air Fibre, Inc. P.O. Box 244 Altadena, CA 91001
Stinson 108 Series T.C. A-767	SA4-1195	Metalized wings.  Issued,	NM-LA	Air Mod 11379 Playa Street Culver City, CA 90230
Stinson 108 Series T.C. A-767	SA4-1210	Installation of Eonnex cover on aircraft surfaces.  Reissued, 08/19/1980	NM-LA	Ceconite, Inc. 4677 Worth St. Los Angeles, CA 90063
Stinson 108 Series T.C. A-767	SA4-1415	Installation of Autopilot  Reissued, 10/01/1973	SW-FW	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
Stinson 108 Series T.C. A-767	SA4-1484	Sheet metal on wings.  Issued, 01/01/1960	NM-LA	Robert B. Everitt 2134 Xavier Santa Clara, CA 95050
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA00081NY	Installation of Iceman Aviation Supplies Inc. Carburetor Ice Detector.  Amended, 05/15/2002	NM-S	Lamar Technologies Corporation 14900 40th Avenue NE Maysville, WA 98271
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA00141LA	Installation of a replacement S&S Propeller model W7848F2-2. Issued, 10/09/1996	NM-LA	S & S Propeller, Inc. 3681 Sacramento St. Suite D San Luis Obispo, CA 93401
Stinson 108-3, 108-5 T.C. A-767	SA00188AT	Installation of Appalachian Accessories carbon steel brake discs that have the melonite surface treatment, P/N AA-26A. Reissued, 11/14/1994	CE-A	Aviation Products, Inc. 1400 E. South Blvd. Montgomery, AL 36116
Stinson 108-3, 108-5 T.C. A-767	SA00191AT	Installation of carbon steel brake discs that have the melonite surface treatment.  Reissued, 11/14/1994	CE-A	Aviation Products, Inc. 1400 E. South Blvd. Montgomery, AL 36116
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA00215NY	Installation of CAVU Model AM100 AVMIX engine fuel/air mixture setting system.	NE-NY	CAVU Products Limited 2325 Mountland Drive Peterborough, Ontario K9K 1W3

Summary of FAA Supplementary Type Certificates  
for Univair Aircraft and the  
Stinson 108 Series.  
T.C. A-767

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	REG.	STC HOLDER
		Amended, 08/14/1995		Canada
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA00402SE	Installation of a remote spin-on oil filter adapter. (GC-1B w/Lycoming or Cont. 360 engine installed) Amended, 04/24/2000	NW-S	Aviation Development Corp. 1305 NW 200th St. Seattle, WA 98177
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA00433	Installation of Airwolf remote mounted engine oil filter Model AFC-500 or AFC-600 on multi engine fixed wing light aircraft incorporating Franklin reciprocating engines of 450 hp. Or less. (with Franklin engines.) Amended, 05/07/1997	CE-C	Airwolf Filter Corporation 15369 Madison Rd. Middlefield, OH 44062
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA00433NY	Installation of Airwolf remote mounted engine oil filter Model AFC-500 or AFC-600 on multi engine fixed wing light aircraft incorporating Franklin reciprocating engines of 450 hp. Or less. Amended, 07/21/1999	CE-C	Airwolf Filter Corporation 15369 Madison Rd. Middlefield, OH 44062
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA00478CH (2 of 3)	Installation of Cooper Superflite 102 Fabric.  Reissued, 07/09/2002	CE-C	Aviation Products Systems, Inc. 3701 Highway 162 Granite City, IL 62040
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA00478CH	Installation of Cooper Superflite 102 Fabric.  Reissued, 07/09/2002	CE-C	Aviation Products Systems, Inc. 3701 Highway 162 Granite City, IL 62040
Stinson 108 Series  T.C. A-767	SA00680SE (2 of 6)	Installation of Electronics International model UBG-16 or UBG-16T bar graph analyzer. Reissued 07/08/2005	NM-S	Electronics International 2012 NW Aeroclek #523 Hillsboro, OR 97124
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA00780SE (2 of 3)	Installation of the True Lock Safety Retention Axle Lock Nut System.  Amended, 04/02/2003	NM-S	True Lock LLC 4911 Parkwood St. Boise, ID 83704-2318
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA00904NY	Installation of Teledyne Continental IO-360 Series engine with constant speed propeller.  Issued, 11/02/1998	NE-NY	Tyee Aero Conversion Limited 7900 Fairview Road Black Creek, B.C. V9J 1G5 Canada
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA01015SE	Installation of eligible Alaska Tire and Rubber Company TSO-C62d Tires as listed in Approved Model List SA01015SE, dated November 7, 2001, or later FAA approved revision. Amended, 04/16/2003	NM-S	Alaskan Bushwheel, Inc. P.O. Box O Joseph, OR 97846
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA01026SE (2 of 2)	Installation of improved fuel gascolator.  Amended, 06/12/2003	NM-S	Steve's Aircraft 15373 Jones Rd. White City, OR 97503
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA01137SE	Installation of vortex generators on the wings and tail surfaces of the above model aircraft in accordance with Drawing Package MA2159, Revision IR, dated February 15, 2002, and Installation Manual MA2160, Revision IR, dated October 9, 2002, or later FAA approved revision to either of these documents. Issued, 10/28/2002	NM-S	Micro AeroDynamics, Inc. 4000 Airport Rd, Suite D Anacortes, WA 98221
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA01229SE (3 of 3)	Installation of CNX80 GPS WAAS Navigator with integrated VHS Navigation and Communi- cation radios.	NM-S	UPS Aviation Technologies 2345 Turner Rd. S.E. Salem, OR 97309

Summary of FAA Supplementary Type Certificates  
for Univair Aircraft and the  
Stinson 108 Series.  
T.C. A-767

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	REG.	STC HOLDER
		Amended 12/21/2004		
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA01229SE (3 of 4)	Installation of CNX80 GPS WAAS Navigator with integrated VHS Navigation and Communication radios.	NM-S	UPS Aviation Technologies 2345 Turner Rd. S.E. Salem, OR 97309
		Amended 04/25/2005		
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA01233SE	Manufacture of Alaskan Bushwheel, Inc. (ABI) tailwheel and fork assembly per ABI Document ABI-3200B, Revision A, dated April 28, 2005 or later FAA approved revision. The tailwheel and fork must be installed in accordance with ABI Installations Instructions ABTFK-II, dated April 19, 2005 or later FAA approved revision.	NM-S	Alaskan Bushwheel, Inc. P.O. Box O Joseph, OR 97846
		Amended 5/10/2005		
Stinson 108 T.C. A-767	SA01365AT	Installation of a Lycoming O-320 150 hp or 160 hp engine and engine mount.	CE-A	Hera Abel 13226 SW 43rd Lane Miami, FL 33175
		Amended, 04/05/2000		
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA01396LA	Installation of new rudder bar bushings and bearings.	NM-LA	Hal's Aircraft 320 Spanish Creek Road Quincy, CA 95971
		Issued 11/09/2002		
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA01487SE (4 of 5)	Installation of a GDL 69 or GDL 69A XM Satellite Receiver in accordance with Garmin Supplemental Type Certificate Master Data List P/N 005-C0217-00, Revision A, Dated December 20, 2004 or later FAA approved revision.	NM-S	AeroMech Incorporated 1616 Hewitt Ave., Suite 312 Everett, WA 98201
		Issued 12/20/2004		
415 Series, F-1, F-1A, A-2, A-2A and M-10 T.C. A-718, A-787	SA01944CH (2 of 2)	Modify airplane to fly on unleaded automotive gasoline, 87 minimum antiknock index, per ASTM Specification D-439 or D-4818 of any volatility class, A through E or 82 UL AVGAS per ASTM D-6227.	CE-C	EAA Aviation Foundation 3000 Poberezny Rd. Oshkosh, WI 54901
		Issued, 03/05/2004		
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA02033AT (1 of 3)	Modification to install an air-oil separator to prevent oil from being aspirated from the engine breather line (47J series w STCs SH4-235SW, SH4-826SW or SH479SW)	CE-A	M-20 Oil Separators LLC 5612 NW 38th Terrace Boca Raton, FL 33496-2719
		Amended, 06/29/2005		
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA02154AK	Installation of UPS Technologies Inc. Apollo MX20 multi-display, P/N 430-0270-500.	NM-S	Garmin AT, Inc. 2345 Turner, S.E. Salem, OR 97309
		Amended 01/12/2005		
Stinson 108 Series T.C. A-767	SA02168AK	Installation of hourmeter airspeed switch. For unpressurized aircraft only. Pressurized aircraft must have pressurization system deactivated.	CE-N	Avalaska, Inc. 4340 Postmark Dr. Anchorage, AK 99502
		Issued, 03/23/2001		
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA02217AK (3 of 5)	Installation of Garmin AT Model GDL 90 UAT Data Link System, in accordance with Garmin AT, Inc., GDL 90 UAT Master Data List P/N 560-0278-01, Revision A, dated November 12, 2004 or later FAA approved revision.	CE-N	Garmin AT, Inc. 2345 Turner, S.E. Salem, OR 97309

Summary of FAA Supplementary Type Certificates  
for Univair Aircraft and the  
Stinson 108 Series.  
T.C. A-767

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	REG.	STC HOLDER
Amended 12/01/2004				
Stinson 108 Series T.C. A-767	SA02520AT	Installation of M-20 Oil Separator, model 600-WP.  Issued, 05/30/2002	CE-A	M-20 Oil Separators LLC 5612 NW 38th Terrace Boca Raton, FL 33496-2719
Stinson 108-2 T.C. A-767	SA0471SE	Installation of Allen Aircraft Products fuel tank selector valve.  Issued, 10/03/1997	NM-S	Bruce R. Plendl 4821 Black Forest Lane Everett, WA 98203-3239
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA09470SC	Installation of Starter Indicator light system.  Issued, 06/18/2001	SW-FW	Texas Skyways, Inc. 308 Boerne Stage Airfield Boerne, TX 78006
Stinson 108-3 T.C. A-767	SA21BO	Installation of engine oil preflight lubrication system.  Issued, 09/15/1994	NE-B	John W. Stephenson 22 Hook Rd. Gilford, NH 03246
Stinson 108 Series T.C. A-767	SA58EA	Conversion of airplane for parachute jumping and aerial photography operations.  Issued,	NE-B	East Coast Aviation Corporation Hanscom Field Lexington, MA 02173
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA71GL (2 of 3)	Installation of air filters per AML No. SA71GL dated April 17, 1995 or latest FAA approved revision on single engine aircraft. Reissued, 06/20/2000	NM-LA	Brackett Aero Filters, Inc. 7052 Government Way Kingman, AZ 86401
Stinson 108-2, 108-3 T.C. A-767	SA74NW	Installation of Edo 248-2440 floats.  Reissued and Amended, 08/01/2001	NM-S	Super Stinson Modifications LLC 13173 S. Spangler Rd. Oregon City, OR 97045
Stinson 108-3 T.C. A-767	SA91NW	Installation of strobe light system with flashtube on rudder tip and power supply in fuselage. Amended, 03/11/1974	NM-S	R. J. Schroers 4479 139th Avenue, S.E. Bellview, WA 98006
Stinson 108 Series T.C. A-767	SA124EA	Shur-Vent fuel tank filler cap.  Issued,	NE-NY	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I. NY 11743
Stinson 108 Series T.C. A-767	SA224SO	Removal of right door for parachute jumping and aerial photography operations.  Issued, 01/01/1960	CE-A	Robert V. Barham 1984 Capri Drive Decatur, GA 30030
Stinson 108 Series T.C. A-767	SA228WE	Removal of right cabin door for parachute jumping and aerial photography operations.  Issued, 01/01/1960	NM-LA	John C. Harrison 2535 Garfield Avenue Carmichael, CA 95608
Stinson 108-3 T.C. A-767	SA238NW	Installation of Madras Air Service super tips.  Issued, 11/25/1975	NM-S	Madras Air Service Route 2, Box 1225 Madras, OR 97741
Stinson 108-1, 108-2, 108-3 T.C. A-767	SA241CH	Install Ceconite 101 fabric.  Reissued, 07/09/2002	CE-C	Aviation Products Systems, Inc. 3701 Highway 162 Granite City, IL 62040
Stinson 108-3 T.C. A-767	SA300CE	Installation of Woodward propeller governors on single and twin engine aircraft. (PA31-325	CE-C	Woodward Governor Company P.O. Box 7014

Summary of FAA Supplementary Type Certificates  
for Univair Aircraft and the  
Stinson 108 Series.  
T.C. A-767

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	REG.	STC HOLDER
		modified per Colemil STC SA 970SO) Amended, 05/14/1992		Rockford, IL 61125-7014
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA308EA	Installation of carburetor ice detection system 105AP in single and twin engine aircraft and single engine helicopters powered Continental Franklin, and Lycoming type engines equipped with Marvel-Schebler MA-2, MA-3, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. (Normal, Utility, and Acrobatic Category airplanes and helicopters equipped with engines and carburetors as described.) Amended, 11/20/1978	NE-NY	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I. NY 11743
Stinson 108-1, 108-2 108-3 T.C. A-767	SA313NW	Installation of Franklin 6A-350-C1 or 6A-350-C2 engine, Hartzell HC-C2YF-1BF/F8459-4 to-8 propeller, Hartzell HC-C2YF-1BF/F8459A-40 to -80, or McCauley 2A31C21/84S-4 to -8 propeller. Reissued, 11/19/1999	NM-D	Franklin Aircraft Engines, Inc. 136 Racquette Drive Ft. Collins, CO 80524
Stinson 108-1, 108-2 108-3 T.C. A-767	SA327SO	Tri-Gear Conversion with Lycoming O-435 series engine per Robinson Report No. R-108-3 and Drawing List No. R-100, Certification Basis is CAR3, effective September 17, 1948 Reissued, 06/12/2003	CE-A	James Winter HC 83 Box 56A Custer, SD 57730
Stinson 108 Series T.C. A-767	SA343WE	8:50X6 4-ply aircraft tires and 8:50X6 tubes.  Issued, 01/01/1960	NM-S	Rex H. Morehouse 4922 Summers Lane Klamath Falls, OR 97601
Stinson 108 Series T.C. A-767	SA463CE	Metal fuselage covering.  Issued, 01/01/1960	CE-W	David Z. Waldemer Flying W Ranch Fairdealing, MO 63936
Stinson 108-2, 108-3, 108-5 T.C. A-767	SA489EA	Installation of ARP Inc. carburetor ice detection Models 107AP (-12, -R-12, -24 and -R-24 series) in single and twin engine aircraft and single engine helicopters powered Continental, Franklin, and Lycoming type engines equipped with Precision Air-Motive (Facet or Marvel- Schebler) MA-2, MA-3, MA-3SPA, MA-4 MA-4-5, MA-4SPA, MA-5, MA-6, MA-6AA and HA-6 series carburetors. Amended, 12/05/2002	NE-NY	Aircraft & Rotorcraft Products (ARP) Inc. 2 Middle Cross Road Shoreham, NY 11786-1440
Stinson 108-3 T.C. A-767	SA511NW	Installation of Franklin 6AS-350-A and 6AS -350-A1 engines, AiResearch TE-0657 tubosupercharger system, and Hartzell HC-C2YF-1BF/F8459A-4 to -8 propellers and HC-C2YF-1BF/F8459A-4Q to -8Q propellers. Reissued, 11/19/1999	NM-D	Franklin Aircraft Engines, Inc. 136 Racquette Drive Ft. Collins, CO 80524
Stinson 108 Series T.C. A-767	SA515CE	Install metal wing covering.  Issued, 01/01/1960	CE-W	David Z. Waldemer Flying W Ranch Fairdealing, MO 63936
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA593CH	Install Unison SlickSTART tm magneto booster system.  Amended, 03/12/2004	CE-C	Unison Industries 530 Blackhawk Park Avenue Rockford, IL 61104

Summary of FAA Supplementary Type Certificates  
for Univair Aircraft and the  
Stinson 108 Series.  
T.C. A-767

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	REG.	STC HOLDER
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA615SO	Surface fabric attachment clips.  Reissued, 06/03/1991	NM-LA	Arbor Company 18382 Avenida Bonita Sonoma, CA
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA637NW	Installation of AC oil filter assembly No. OF-104 and Champion oil filters P/N CH48108 and CH48109. Reissued, 04/27/1995	CE-W	Li'l Red Aero Route 1, Box 120 Municipal Airport Kearney, NE 68847
Stinson 108 Series T.C. A-767	SA666NW	Installation of Teflon control yoke bushings.  Amended, 05/15/1996	NM-S	George O. Johnson 28102 150th Avenue East Graham, WA 98338
Stinson 108-1 T.C. A-767	SA714NW	Installation of a Continental IO-360C engine and a McCauley 2A34C203/90DCA-8 propeller.  Reissued, 03/19/2004	CE-N	Wayne C. Alsworth, Jr. P.O. Box 268 Sterling, AK 99672
Stinson 108 Series T.C. A-767	SA798EA	Installation of Monitair exhaust gas combustion monitor kit.  Reissued, 02/14/1972.	CE-C	Rosemount Engineering Co. 12001 West 78th Street Eden Prairie, MN 55343
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA799WE	Installation of George M. Adams DGA-2000 or Bodell BMI-2000 wheel assemblies in lieu of Firestone wheel assembly No. DFA 180. (DGA-2000 wheel approved under TSO-C26a.) Reissued, 06/25/2003	NM-LA	Skybound Manufacturing, Inc. 6910-A Buford Highway Doraville, GA 30340
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA800EA (1 of 2)	Installation of Aviation White Anti-Collision Strobe Lights. Whelen Models A429, A430, A434, A450, A408 (white), A408R/W or A470R/W (red/white), A500, A625, or A650 and associated power supplies or Model SA strobe light system. Amended, 06/17/2005	NE-B	Whelen Engineering Co. Inc Route 145 Winthrop Road Chester, CT 06412-0684
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA859SO	Replacement of generator P/N1101877 installed in Franklin 6A-150 and -165 engines with a modified Motorola RA12N550 alternator. Issued, 10/20/1975	CE-A	Stanley C. Bedford 2396 Santa Cruz Drive Clearwater, FL 33516
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA899GL	Superseded by STC SA01944CH. Modify airplane to fly on unleaded automotive gasoline, 87 minimum antiknock index. Surrendered, 03/05/2004	CE-C	EAA Aviation Foundation P.O. Box 2591 Wittman Airfield Oshkosh, WI 54903-3065
Stinson 108-1, 108-2 108-3 T.C. A-767	SA906NM	Installation of addition Harrison oil cooler (Franklin P/N P-6761) and associated systems.  Amended, 04/06/1999	CE-W	Li'l Red Aero, Inc. Route 1, Box 120 Municipal Airport Kearney, NE 68847
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA963NW	Lycoming O-360-A1A, Sensenich 76EM8-0-56 propeller, cross over exhaust, modified carburetor inlet in accordance with Alpine Aviation Installation Instructions and Drawing List P/N 80108, Revision 3, dated 4/15/82 and/or later FAA approved revisions. Issued, 07/23/1980 Reissued 04/28/2005	NM-S	Lands Inn, LLC 45457 D.C. Lane Kimberly, OR 97848

Summary of FAA Supplementary Type Certificates  
for Univair Aircraft and the  
Stinson 108 Series.  
T.C. A-767

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	REG.	STC HOLDER
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA964NW	Lycoming O-360-A1A, Hartzell HC-C2YK-1BF/F766A propeller, cross over exhaust, carburetor inlet in accordance with Alpine Aviation Installation Instruction Manual P/N 80109, Report No. 2, dated February 20, 1982 and/or later FAA approved revisions. Issued, 07/23/1980 Reissued 04/28/2005	NM-S	Lands Inn, LLC 45457 D.C. Lane Kimberly, OR 97848
Stinson 108 Series T.C. A-767	SA1008WE	Installation of Poly-Fiber covering material.  Reissued, 05/27/2003	NM-LA	Poly-Fiber, Inc. 4343 Fort Dr. Riverside, CA 92509-3129
Stinson 108, 108-1, 108-2, 108-3 T.C. A-767	SA1120GL	Surrendered and incorporated into STC SA00478CH.  Surrendered, 06/14/2002	CE-C	AAR 1111 Nicholas Blvd. Elk Grove, IL 60007
Stinson 108 Series T.C. A-767	SA1177WE	WEBCO carburetor temperature monitor.  Issued, 01/01/1960	NM-LA	Richard P. Winnen 21318 Grace Avenue Torrance, CA 90501
Stinson 108-2, 108-3 T.C. A-767	SA1199WE	Installation of Continental O-470-A, -J, -K, -L, or -R engine and McCauley 2A34C/90A or 2A36C/90M propellers: or O-470A, -J, -K, or -L engine and Hartzell HC-A2XF-1/8433 or BHC-A2XF-1/8433 propellers, or O-470-R engine and Hartzell BHC-C2Y/8468 propeller. (108-3 land and seaplanes) Reissued and Amended, 08/01/2001	NM-S	Super Stinson Modifications, LLC 13173 S. Spangler Rd. Oregon City, OR 97045
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA1315WE (2 of 2)	Installation of Tri-Star Corp. mixture monitor (exhaust gas temperature probe, gage and selector). Reissued, 10/10/1985	NM-D	Universal Corporation 730 Independent Avenue Grand Junction, CO 81505
Stinson 108 Series T.C. A-767	SA1350WE	Replace existing fabric on wings, fuselage, empennage and/or control surfaces with fiberglass cloth. Reissued, 03/06/1969	NM-LA	Ceconite, Inc. 4677 Worth St. Los Angeles, CA 90063
Stinson 108, 108-1, 108-2 T.C. A-767	SA1351WE	Replace existing fabric on wings, fuselage, empennage and/or control surfaces with Ceconite 101 material (262A Series - 12) Amended, 08/19/1983	NM-LA	Ceconite, Inc. 3815 Medford St. Los Angeles, CA 90063
Stinson 108-1, 108-2 108-3 T.C. A-767	SA1495GL	Install Aero Fabricators shoulder harness and seat belt assembly.  Issued, 06/28/1990	CE-C	Aero Fabricators, Co. 1216 North Rd. Lyons, WI 53148
Stinson 108 Series T.C. A-767	SA1512WE	Installation of exhaust gas temperature monitoring systems Model EGT-1.  Amended, 08/23/1974	NM-LA	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
Stinson 108-3 T.C. A-767	SA1552NM	Installation of Lycoming IO-360(200 hp) engine, Hartzell constant speed propeller HC-C2YK/7666, and associated changes. Issued, 05/13/1983	NM-D	Univair Aircraft Corporation 2500 Himalaya Road Aurora, CO 80011
Stinson 108 Series T.C. A-767	SA1626NM (2 of 2)	Installation of Electronics Int'l Digital EGT/CHT Instruments and accessories. (201 Series)	NM-S	Electronics International 5289 Elam Young Pkwy. #G200



Summary of FAA Supplementary Type Certificates  
for Univair Aircraft and the  
Stinson 108 Series.  
T.C. A-767

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	REG.	STC HOLDER
				Hillsboro, OR 97124
		Amended, 05/09/1993		
Stinson 108-2, 108-3 T.C. A-767	SA1647NM	Installation of EDO Model 44-2425 seaplane floats and auxiliary fin (108-3901002).	NM-D	Franklin Aircraft Engines, Inc. 136 Racquette Drive Ft. Collins, CO 80524
		Reissued, 11/19/1999		
Stinson 108-2, 108-3 T.C. A-767	SA1666NM	Installation of a Franklin 6A-335-B or 6A-335-B1 engine, McCauley 2A31C/84S-4 to -8 propeller, spinner and associated systems. Modifications includes installation of a 40 amp alternator, Model SFA 5582.	NM-D	Franklin Aircraft Engines, Inc. 136 Racquette Drive Ft. Collins, CO 80524
		Reissued, 07/02/2001		
Stinson 108 Series T.C. A-767	SA2105WE	Installation of Model EGT-3 exhaust gas temperature monitor (with rising temperature alarm).	NM-LA	K S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
		Issued, 02/09/1970		
Stinson 108, 108-1 108-3 T.C. A-767	SA2128CE	Operation of airplane on unleaded automotive gasoline, 87 minimum antiknock index and leaded automotive gasoline, 88 minimum antiknock index (RON=MON)/2. Intermixing with aviation gasoline also approved.	CE-W	Petersen Aviation, Inc. Route 1, Box 18 Minden, NE 68959
		Amended, 06/23/1992		
Stinson 108-3, 108-5 T.C. A-767	SA2335SO	Installation of Appalachian Accessories P/N 73-5 brake discs.	CE-A	Aviation Products, Inc. 1400 E. South Blvd. Montgomery, AL 36116
		Reissued, 09/29/1995		
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA2557NM	Installation of KS Avionics EGT/CHT-2( ) combined exhaust gas and cylinder head temperature monitoring system.	NM-LA	K S Avionics, Inc. 25216 Cypress Avenue Hayward, CA 94544
		Amended, 01/12/1995		
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA2666WE	Ceconite 102 material covering complete aircraft. (262A SERIES-12)	NM-LA	Ceconite, Inc. 3815 Medford St. Los Angeles, CA 90063
		Amended, 08/19/1983		
Stinson 108-2, 108-3 T.C. A-767	SA2683NM	Installation of Precise Flight, Inc. stand-by vacuum system (SVS)	NM-S	Precise Flight, Inc. 63354 Powell Butte Road Bend, OR 97701
		Amended, 11/03/2003		
Stinson 108 Series T.C. A-767	SA2718NM	Installation of Lycoming O-360 (180 HP) engine, Sensenich fixed pitch propeller 76EM8.	NM-D	Univair Aircraft Corporation 2500 Himalaya Road Aurora, CO 80011
		Amended, 11/13/1985		
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA2844CE	Installation of a plastic cap enclosure over the anti-collision strobe light system.	CE-W	Air Transport, Inc. 1015 N. Carlton Liberal, KS 67901
		Issued, 07/29/1992		
Stinson 108-3, 108-5 T.C. A-767	SA3203SO	Replacement of Cleveland brake disks, P/N 164-26A, and/or 164-126A, with Appalachian Accessories stainless steel brake disks P/N 75-27.	CE-A	Aviation Products, Inc. 1400 E. South Blvd. Montgomery, AL 36116
		Reissued, 09/29/1995		
Stinson 108-1, 108-2, 108-3 T.C. A-767	SA3531NM	Installing copper electrical cables.	NM-S	Bogert Aviation 308 S. Perry Place Kennewick, WA 99336
		Amended, 04/01/1999		

Summary of FAA Supplementary Type Certificates  
for Univair Aircraft and the  
Stinson 108 Series.  
T.C. A-767

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	REG.	STC HOLDER
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA3631NM	Application of polyurethane finishing system.  Issued, 04/15/1987	CE-N	Talkeetna Aero Services, Inc. P.O. Box 433 Talkeetna, AK 99676
Stinson 108 Series T.C. A-767	SA3862NM	Installation of Electronics Int'l Primary TIT/EGT/CHT instruments, remote switches and associated accessories Amended, 04/25/1988	NM-S	Electronics International 5289 Elam Young Pkwy. #G200 Hillsboro, OR 97124
Stinson 108, 108-1 108-2 T.C. A-767	SA4005NM	Installation of Precise Pulselite control unit in landing/taxi system.  Amended, 11/07/2003	NM-S	Precise Flight, Inc. 63354 Powell Butte Road Bend, OR 97701
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA4172NM	Installation of Aviation Development oil filter.  Amended, 09/01/1999	NM-S	Aviation Development Corp. 1305 NW 200th Street Seattle, WA 98177
Stinson 108 Series T.C. A-767	SA4302NM (2 of 2)	Installation of Electronics Int'l digital automatic engine analyzer.  Amended, 03/05/1993	NM-S	Electronics International 5289 Elam Young Pkwy. #G200 Hillsboro, OR 97124
Stinson 108 T.C. A-767	SA5656NM	Installation of burglar alarm system.  Amended, 07/21/1993	NM-S	Harold S. Thompson P.O. Box 2361 Gig Harbor, WA 99206
Stinson 108-3 T.C. A-767	SA5677NM	Replacement of original vertical stabilizer skins with smooth skins and internal stiffeners.  Issued, 02/05/1992	NM-S	Byron W. Miller 1754 Pine Street Silverton, OR 97381
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA5924NM	Installation of RPM instrument.  Amended, 06/03/1994	NM-S	Electronics International 5289 Elam Young Pkwy. #G200 Hillsboro, OR 97124
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA5925NM	Installation of oil pressure/temperature instrument.  Amended, 06/03/1994	NM-S	Electronics International 5289 Elam Young Pkwy. #G200 Hillsboro, OR 97124
Stinson 108, 108-1, 108-2, 108-3, 108-5 T.C. A-767	SA7965SW	Application of fabric and polyurethane finishing system.  Amended, 04/07/1994	SW-FW	Air Tech Coatings 2300 Redmond Road Jacksonville, AR 72076
Stinson 108 Series T.C. A-767	SA8075SW	Installation of fiberglass covering.  Amended, 03/31/1997 Reissued 11/10/2003	SW-FW	Razorback Fabrics, Inc. 2179 Elmont Road Maynard, AR 72444-9688